

Erledigt

USB 3.0 Problem scheinbar seit 10.11.1 leichter zu beheben

Beitrag von „Jono“ vom 7. Dezember 2015, 23:20

Ich muss gestehen, ich bin noch totaler Anfänger in Sachen Hackintosh und sehe da auch nicht wirklich mit den Hardware IDs durch.

Hab jetzt mal unter Windows nachgeschaut und folgendes gefunden:

Code

1. Fresco Logic xHCI (USB3) Controller FL1000 Series
- 2.
- 3.
4. DriverKey: {36fc9e60-c465-11cf-8056-444553540000}\0011
5. VendorID: 1B73
6. DeviceID: 1000
7. SubSysID: 10001D5C
8. Revision: 01
- 9.
- 10.
11. Debug Port Number: None
12. Bus.Device.Function (in decimal): 3.0.0
- 13.
- 14.
15. Host Controller Power State Mappings
16. System State Host Controller Root Hub USB wakeup Powered
17. S? (unmapped) S? (unmapped) S? (unmapped)
18. S? (unmapped) S? (unmapped) S? (unmapped)
19. S? (unmapped) S? (unmapped) S? (unmapped)
20. S? (unmapped) S? (unmapped) S? (unmapped)
21. S? (unmapped) S? (unmapped) S? (unmapped)
22. Last Sleep State S? (unmapped)

Alles anzeigen

Bringen mir diese Infos jetzt was?