

USB 3.0 Patch + OS X El Capitan

Beitrag von „al6042“ vom 23. August 2016, 19:54

Hi,

dein Board hat den Intel 7 XHCI Controller und den VIA Controller für USB3.0 eingebaut.

Zitat

Chipset:

Up to 4 USB 3.0/2.0 ports (2 ports on the back panel, 2 ports available through the internal USB header)

Up to 6 USB 2.0/1.1 ports (available through the internal USB headers)

VIA VL800 chip:

Up to 4 USB 3.0/2.0 ports on the back panel

* Due to a Windows 7 limitation, please connect your USB device(s) to the Intel controlled USB port(s) (located below the RJ-45 LAN port) before the VIA USB 3.0 controller driver is installed.

Alles anzeigen

Letzterer kann eventuell mit dem GenericUSBXHCI.kext zum Leben erweckt werden... 😊

Habe mal noch schnell eine DSDT zusammen gestellt und beigefügt.