Nach Sleep -> Restart zum Bios / Dell Optiplex 9020

Beitrag von "brousseau6933" vom 22. April 2018, 21:29

Unfortunately, kernel panic when waking in HS. I've stayed with Sierra for this reason.

I tried to insert a compiled SSDT for my i7 4770 but it stays in the 3 gHz range, thus the reason I inject p-states and c-states with Clover instead. It's why I would need your full efi folder to look what you did differently to have pm working with your SSDT. BTW, fine working little computer for doing audio work in my case... Thanks!