

Erledigt

i5 6600k taktet nur bis 3,6ghz aka kein Turboboost

Beitrag von „ozw00d“ vom 5. Januar 2019, 02:25

Mal ein Auszug von Intel:

Intel® Turbo Boost Technology 2.01 automatically allows processor cores to run faster than the rated operating frequency if they're operating below power, current, and temperature specification limits.

Intel Turbo Boost Technology 2.0 is activated when the Operating System (OS) requests a frequency higher than the rated frequency of the processor. Whether the processor enters into and the amount of time the processor spends in the Intel Turbo Boost Technology 2.0 state depends on the workload and operating environment.