

Erledigt

Nach Update auf 10.14.5 kein USB3 mehr?

Beitrag von „gerox“ vom 5. April 2019, 13:43

Mac

schau mal hier vielleicht ist das hilfreich

<https://hackintosh.com/guide...ave-10-14-3-update-guide/>

Auszug aus dem o.a. LINK -->>>

" Hackintosh 10.14.3 USB Patch

High Sierra 10.14.3 uses the same USB patch from 10.14.1 to get all USB/USB3 ports recognized and working. You will also need USBInjectAll.kext if you don't already have it. However for proper USB 3 speeds you may need to create your own SSDT with Mojave 10.14.1+

Mount EFI Partition with Clover Configurator

Navigate to /Volumes/EFI/EFI/Clover/

Right-click open config.plist with Clover Configurator

Click Kernel and Kext Patches under SECTIONS of Clover Configurator

Click the "+" button near the bottom to add this patch:

Name*: com.apple.driver.usb.AppleUSBXHCI

Find* [HEX]:83FB0F0F 83030400 00

Replace* [HEX]: 83FB0F90 90909090 90

Comment: USB 10.14.1+ by PMHeart

MatchOS: 10.14.x

Save config.plist

Download the latest release of Lilu.kext

Paste Lilu.kext into /Volumes/EFI/EFI/Clover/kexts/Other ..."

Ig gerox 