

Dell Vostro 5370

Beitrag von „tprimus“ vom 11. April 2019, 13:21

Ne, habe ich noch nicht. Nur da zu kopieren und rechte neu erbauen?

Jetzt hat schon wieder nach Hause gegangen:

Code

1. New Bluetooth Module published.
2. New Bluetooth Module published.
3. Adam Raczkevy's Mouse connected, handle: 0xC
4. Apr 11 12:41:32 tpa-macbook-pro com.apple.xpc.launchd[1] (com.apple.powerd.swd): Service only ran for 0 seconds. Pushing respawn out by 30 seconds.
5. Apr 11 12:41:32 tpa-macbook-pro Bluetooth Explorer[2082]: Vendor Broadcom Corp Product Broadcom Bluetooth 4.0 USB idVendor 489 idProduct E07A LocationID 14600000
6. Apr 11 12:41:33 tpa-macbook-pro systemstats[52]: assertion failed: 18D109: systemstats + 676139 [952918BC-3D73-37CE-8C6A-851AAF3C70D1]: 0x7ffcd5e12310
7. Apr 11 12:41:33 tpa-macbook-pro kcm[9887]: DEPRECATED USE in libdispatch client: Setting timer interval to 0 requests a 1ns timer, did you mean FOREVER (a one-shot timer)?; set a breakpoint on _dispatch_bug_deprecated to debug
- 8.
9. 2019-04-11 10:41:34 +0000 Mode change 12 for handle: 0x2
10. 2019-04-11 11:16:17 +0000 Mode change 12 for handle: 0x0
11. 2019-04-11 11:16:17 +0000 Mode change 12 for handle: 0x2
12. Adam Raczkevy's Mouse disconnected
13. Bluetooth Module powered off.
14. Bluetooth Module powered off.
15. HCI Controller terminated; module unplugged or firmware reset/crashed.
16. HCI Controller terminated; module unplugged or firmware reset/crashed.
17. Error getting HCI transport info: E00002D7
18. Error getting HCI transport info: E00002D7
19. Apr 11 13:16:18 tpa-macbook-pro Bluetooth Explorer[2082]: Vendor Broadcom Corp Product Broadcom Bluetooth 4.0 USB idVendor 489 idProduct E07A LocationID 14600000
20. Apr 11 13:16:19 tpa-macbook-pro kcm[10011]: DEPRECATED USE in libdispatch client: Setting timer interval to 0 requests a 1ns timer, did you mean FOREVER (a one-shot timer)?; set a breakpoint on _dispatch_bug_deprecated to debug
- 21.
22. Error getting HCI transport info: E00002D7
23. Error getting HCI transport info: E00002D7

24. Error getting HCI transport info: E00002D7

Alles anzeigen

Was merkwürdig ist, dass es mit external Bluetooth auch passieren kann. Das bedeutet, dass das Problem sollte mit den Bluetooth controller sein...