

# Gigabyte Z390 DESIGNARE: fertiger Clover-EFI-Ordner zum Download

Beitrag von „TobiasH“ vom 5. November 2019, 18:54

[Zitat von JimSalabim](#)

Wobei das Problem von [TobiasH](#) auch ein anderes sein könnte. Du meinst aber nicht, dass die externe Platte nach dem Ruhezustand nicht korrekt ausgeworfen wird? Das wiederum liegt am zu schnellen RAM und sieht gerne mal so aus: 😄

Beide angesprochene Möglichkeiten kann ich ausschließen, da ich die IMac Pro Variante nutze und den Ruhemodus deaktiviert hatte.

[Seit ich diese Änderung getätigt habe, läuft der Rechner ununterbrochen ohne Probleme. \(Zufall?\)](#)

## [USBInjectAll.kext Catalina 10.15.0 \(2 Patches\)](#)

- Patch #1:
- Name\*: **com.apple.iokit.IOUSBHostFamily**
- Find\* [HEX]: **83FB0F0F**
- Replace\* [HEX]: **83FB3F0F**
- Comment: **USB Port Limit Patch 1 PMHeart/DalianSky**
- MatchOS: **10.15.x**
- Patch #2:
- Name\*: **com.apple.driver.usb.AppleUSBXHCI**
- Find\* [HEX]: **83F90F0F**
- Replace\* [HEX]: **83F93F0F**
- Comment: **USB Port Limit Patch 2 PMHeart/DalianSky**
- MatchOS: **10.15.x**

## **Catalina 10.15.0 (2 Patches)**

- Patch #1:
- Name\*: **com.apple.iokit.IOUSBHostFamily**
- Find\* [HEX]: **83FB0F0F**
- Replace\* [HEX]: **83FB3F0F**
- Comment: **USB Port Limit Patch 1 PMHeart/DalianSky**
- MatchOS: **10.15.x**

- Patch #2:
- Name\*: **com.apple.driver.usb.AppleUSBXHCI**
- Find\* [HEX]: **83F90F0F**
- Replace\* [HEX]: **83F93F0F**
- Comment: **USB Port Limit Patch 2 PMHeart/DalianSky**
- MatchOS: **10.15.x**