

# Gigabyte RX 5700XT 8GB OC / Gigabyte Z390 Gaming X / i5 9600KF / Catalina 15.2 : Problem vor der ersten Installation (Erster Hackintosh)

Beitrag von „Marfti“ vom 12. Januar 2020, 00:23

Hey, ich bin schon ein bisschen weiter gekommen

den Basis Ordner hab ich von al6042, also der CFL...

```
en0::IO80211Interface::postMessage bssid changed
bpfAttach len 94 dlt 163
bpfAttach len 30 dlt 105
bpfAttach len 52 dlt 127
bpfAttach len 36 dlt 192
_dll_attach_flowswitch_nexus: en0 1500 1500
AirPort_BrcmNIC::getSSIDData(): Get failure: APPLE80211_IOC_SSID: 6
IOConsoleUsers: time(0) 0->0, lIn 0, lIk 1,
IOConsoleUsers: gIOScreenLockState 3, hs 0, bs 0, now 0, sm 0x0
en0: setting diversity to: -1
en0: Error configuring antenna diversity (index = -1).
en0: setting tx antenna: -1
en0: Error configuring transmit antenna (index = -1).
en0: channel changed to 1
Forcing CS_RUNTIME for entitlement: com.apple.private.security.storage.TimeMachine.heritable
Sat Jan 11 22:45:23 2020 iMac.local com.apple.xpc.launchd[1] (com.apple.xpc.launchd.domain.plist.diskmanagementd.594) <Error>: Failed to bootstrap path: path = /usr/lib
en0: 802.11d country code set to 'DE'.
en0: Supported channels | 2 3 4 5 6 7 8 9 10 11 12 13 36 40 44 48 52 56 60 64 100 104 108 112 116 120 124 128 132 136 140 149 153 157 161Sat Jan 11 22:45:30 2020 iMac
ed with abnormal code: 1
apfs_module_stop:1724: unload: com.apple.filesystems.apfs, v1412.61.1, apfs-1412.61.1, 2019/11/20 (remaining mem allocated: 0)
considerRebuildOfPrelinkedKernel com.rehabman.driver.USBInjectAll triggered rebuild
Forcing CS_RUNTIME for entitlement: com.apple.private.security.kext-management
```