

Erledigt

Habe Probleme mit der Installation von macOS auf meinem PC mit dem MSI Z390-A Pro und der RX 5700

Beitrag von „Luoke1“ vom 16. März 2020, 18:40

muster48 Habe ich gemacht...

Entweder hat es nicht geklappt /oder

es hat funktioniert und es hat sich ein neues Problem aufgetan.

Hier ein Bild des Codes:

```
Start InitDeviceTree
End InitDeviceTree
Start InitMemoryConfig
End InitMemoryConfig
Start CheckHibernate
End CheckHibernate
efiboot loaded from device: Acpi(PNP0A03,0)/PCI(14|0)/USB(9, 0)/HD(Part2.SI
efiboot file path: \System/Library\CoreServices\boot.efi
Start OpenVolume
End OpenVolume
Start ProcessOptions
End ProcessOptions
RegisterRestartDataProtocol: called. 0x079b0a18
RestartData protocol installed successfully.
Start SetConsoleMode
End SetConsoleMode
Start ReadKernelCache
End ReadKernelCache
Start UncompressKernelCache
End UncompressKernelCache
Start CalculateMdr32
End CalculateMdr32
Start LoadKernelFromStream
Error allocating 0x260 pages at 0x00000000fe00000 alloc type 2
End LoadKernelFromStream
ERROR!!! Load prelinked kernel with status 0x0000000000000009
Error loading kernel cache (0x9)
```