

macOS erkennt keine Platten mehr

Beitrag von „5T33Z0“ vom 23. Oktober 2021, 00:32

Würd's mal mit diesem UEFI Quirk versuchen:

UnblockFsConnect

Description: Some types of firmware block partition handles by opening them in By Driver mode, resulting in an inability to install File System protocols.

Note: This quirk is useful in cases where unsuccessful drive detection results in an absence of boot entries.