

OpenCore Sammelthread (Hilfe und Diskussion)

Beitrag von „5T33Z0“ vom 29. Oktober 2021, 20:31

[kaisteffen](#): liegt an Monterey.

Vorhin folgende Message erhalten:

Zitat

Unfortunately they changed the way to detect wifi on monterey by adding IO80211FamilyLegacy.kext, that currently no kexts e.g. HS80211Family does not work, despite inserting the string IO80211FamilyLegacy, it does not crash at startup normal part but does not detect anything and from the beta version that I have done so many tests all the procedures I know, nothing to do. It only works up to Big Sur, I currently use a Wifi dongle for Monterey, hoping someone will create an updated kexts to detect Atheros cards.