

Anfrage aus dem HWC - Dell Latitude 7280

Beitrag von „ende4711“ vom 1. November 2021, 10:36

I can speak only for Dell 7730:

Intel Wireless & Bluetooth Modul as build in AC 9260 is working.

With Monterey Wireless is working quite well the issue I have is the BT module there are still some issues.

The single Thunderbolt plugs will work once you started up it in Monterey. Thunderbolt hot plug in is not working.

In my point of view the key set point of Dell are the right SSDT ACPI configuration for that.

Just tested the Dell Dockingstation TB18DC works quite well with USB, HDMI etc. with Monterey plugged in before start up.