

Ryzen 5 5600x und RX 6900 xt

Beitrag von „fabiosun“ vom 29. Juli 2022, 21:41

[tackerjim](#) a simple try is to detach ethernet cable.

you have this ethernet on board RTL8125BG

I do not know if it is supported well in Monterey