

AQ-107C unter macOS Monterey 12.3

Beitrag von „kaneske“ vom 20. September 2022, 19:41

AppleVTD needs to be functional.

Enable VT-D equivalent in BIOS and your Problem is gone.