

Plötzlich kein WIFI mehr :- (BCM943602cs

Beitrag von „byebye123“ vom 17. April 2023, 10:42

Hast ja schon gelesen aber auch umgesetzt?:

- **If you've flashed the custom firmware for the Intel I225-V Controller**, it doesn't matter if you drop, replace or keep the stock DMAR table - it will work, as long as `Vt-d` is enabled and `DisableIoMapper` is set to `false`. 3rd Party Wifi/Ethernet cards may still require aforementioned memory regions, so it's best to not drop/replace the DMAR table!
- `Vt-d` (Bios) enable
- `DisableIoMapper` is set to `false` (OC Config)
- 3rd Party Wifi-not drop/replace the DMAR table! (OC Config)

Dann evtl. noch:

[Performance Ventura Monterey](#)