

FUJITSU CELSIUS R930 WORKSTATION CHIPSET: INTEL® C602. (X79) E5-2697V2 MONTEREY WILL NOT BOOT

Beitrag von „kobiemexx2“ vom 26. August 2023, 07:46

This a German workstation

FUJITSU CELSIUS R930 Workstation

Mainboard type : D3118. Chipset: Intel® C602. (X79)

2x Intel® Xeon® processor E5-2697v2 (12 cores, 2.70 GHz, 30 MB)

16GB (1 module(s) 16GB) DDR3, registered, ECC, 1,600 MHz, PC3-12800 (16x)

AMD Radeon Pro W5700 8GB GDDR6

LAN: 2x Built-in 10/100/1,000 MBit/s Intel® 82579 LM and Intel® 82574L

Audio codec : Conexant CX20642

USB 2.0 total. :11,USB 3.0 total : 2,USB front : 4 (2x USB 3.0),USB rear : 6,USB internal: 1

Big Sur works fine but Monterey just keeps restarting on boot .

Any help will be appreciated (Ich freue mich wenn jemand Auf Deutsch Helfen können)

thanks