

# Mac Pro 5.1 Ventura/Sonoma AMD Radeon Pro W5700 8 GB

Beitrag von „crashT“ vom 2. Dezember 2023, 17:20

[Zitat von Bob-Schmu](#)

Erst mal solltest du den verbose Mode aktivieren und davon ein Screenshot hochladen, dann weiß man wo der hängt oder ein Debug log wäre noch besser.

NootRX kext macht die ganze Sache nicht besser, da dein Pro W5700 schon native von macOS unterstützt wird.

Danke Bob für Deine Geduld.

verbose Mode -> Wo? -> hab im OCP was gefunden und probiere das aus

Debug log -> wo, und wie komme ich danach an die Logs? -> hier gilt das gleiche, wie man dann an die Logs kommt weiß ich noch nicht

Hier mal die config aus dem OCP:

Building Configuration for external: MacPro5,1

Build folder already present, skipping

Deleting old copy of OpenCore folder

- Adding OpenCore v0.9.6 DEBUG
- Adding config.plist for OpenCore
- Adding Lilu.kext 1.6.7
- Enabling Rosetta Cryptex support in Ventura
- Adding CryptexFixup.kext 1.0.2
- Adding SurPlus Patch for Race Condition
- Adding NoAVXFSCompressionTypeZlib.kext 12.3.1

- Adding NoAVXFSCompressionTypeZlib-AVXpel.kext 12.6
- Enabling legacy power management support
- Adding AppleIntelCPUPowerManagement.kext 1.0.0
- Adding AppleIntelCPUPowerManagementClient.kext 1.0.0
- Overriding ACPI SMC matching
- Adding ASPP-Override.kext 1.0.1
- Adding ExFatDxeLegacy.efi
- Adding USB 3.0 Controller Patch
- Adding XhciDxe.efi and UsbBusDxe.efi
- Enabling CSM support
- Adding PCI Bus Enumeration Patch
- Adding AppleMCEReporterDisabler.kext 1.0.0
- Adding Intel82574L.kext 1.0.0
- Adding ECM-Override.kext 1.0.0
- Adding CatalinaIntelI210Ethernet.kext 1.0.0
- Enabling BCM94328 Networking Support
- Adding corecaptureElCap.kext 1.0.1
- Adding IO80211ElCap.kext 2.0.0
- Adding WhateverGreen.kext 1.6.6
- Adding Mac Pro, Xserve DRM patches
- Adding AppleALC.kext 1.6.3
- Adding AppleGraphicsPowerManagement Override
- Adding KDKlessWorkaround.kext 1.0.0
- Fixing Legacy Bluetooth for macOS Monterey
- Adding BlueToolFixup.kext 2.6.8
- Adding Bluetooth-Spoof.kext 1.0.0

- Adding SATA Hibernation Patch
- Enabling SMC exemption patch
- Adding SMC-Spoof.kext 1.0.0
- Adding ipc\_control\_port\_options=0 to boot-args
- Adding AutoPkgInstaller.kext 1.0.3
- Set [SIP](#) to allow Root Volume patching
- Allowing FileVault on Root Patched systems
- Enabling KC UUID mismatch patch
- Adding RSRHelper.kext 1.0.0
- Disabling AMFI
- Adding CSLVFixup.kext 2.6.1
- Disabling SecureBootModel
- Enabling AMFIPass
- Adding AMFIPass.kext 1.4.0
- Adding FeatureUnlock.kext 1.1.5
- Adding additional FeatureUnlock args: -disable\_sidecar\_mac
- Disabling memory error reporting
- Setting RestrictEvents block arguments: pcie
- Adding RestrictEvents.kext 1.1.3
- Setting RestrictEvents patch arguments: sbvmm
- Adding USB-Map.kext
- Adding UHCI/OHCI USB support
- Enabling Verbose boot
- Enabling DEBUG Kexts
- Adding DebugEnhancer.kext 1.0.8
- Enabling DEBUG OpenCore

- Adding CPUFriend.kext 1.2.7
- Adding OpenCanopy GUI
- Adding bootmgfw.efi BlessOverride
- Enabling SMC exemption patch
- Setting macOS Monterey Supported SMBIOS
- Using Model ID: MacPro7,1
- Using Board ID: Mac-27AD2F918AE68F61
- Using Minimal SMBIOS patching
- Setting Firmware Feature: 8e81fe137
- Cleaning up files
- Validating generated config

#####

beim erneuten Booten ist vom verbose Mode nichts zu sehen, alles wie immer = Logo + 50% Balken - nicht mehr und nicht weniger