

Probleme mit erster eigener EFI

Beitrag von „ST3R30“ vom 15. März 2025, 14:24

[Triso01](#)

Probier's mal mit dem Standard-Framebuffer-patch:

| | | |
|-----------------------------|--------------|-------------------|
| ▼ PciRoot(0x0)/Pci(0x2,0x0) | ‡ Dictionary | 3 key/value pairs |
| AAPL,ig-platform-id | ‡ Data | <00001219> |
| framebuffer-patch-enable | ‡ Data | <01000000> |
| framebuffer-stolenmem | ‡ Data | <00003001> |

Code

1. <dict>
2. <key>PciRoot(0x0)/Pci(0x2,0x0)</key>
3. <dict>
4. <key>AAPL,ig-platform-id</key>
5. <data>AAASGQ==</data>
6. <key>framebuffer-patch-enable</key>
7. <data>AQAAAA==</data>
8. <key>framebuffer-stolenmem</key>
9. <data>AAAwAQ==</data>
10. </dict>