

Hackintosh stürzt nach kurzer zeit ab

Beitrag von „Fyynn“ vom 17. November 2022, 11:10

Moin,

und zwar habe ich gestern Ventura installiert.

Installation ist auch ohne Probleme durchgelaufen.

Allerdings is er direkt nach der Installation nach ca.5 min abgestürzt und hat sich neu gestartet.

Mittlerweile stürzt er schon nach ca. 30 sec. nach dem einloggen ab.

Hab gehört es soll irgendwas mit dem Ethernet anscheinend sein aber herausgefunden habe ich leider nicht viel.

Opencore Version ist 0.8.6

Wäre für Hilfe sehr dankbar

LG 😊

Beitrag von „Bob-Schmu“ vom 17. November 2022, 11:14

OC Ordner mal hochladen

Beitrag von „Aluveitie“ vom 17. November 2022, 11:47

DummyPowerManagement Quirk aktiviert?

Beitrag von „Fyynnn“ vom 17. November 2022, 16:29

[Aluveitie](#) ja hab ich

Resources Ordner hab ich mal gelehrt sonst wär die Datei zu groß

Beitrag von „fabiosun“ vom 17. November 2022, 16:40

try to disconnect your ethernet cable

Beitrag von „Fyynnn“ vom 17. November 2022, 16:46

[fabiosun](#) still crashing

Beitrag von „Bob-Schmu“ vom 17. November 2022, 17:26

@[Fyynnn](#) das ganze ging wohl schief, man kann so ein OC Ordner auch in mehrere Parts komprimieren, wenn er zu groß ist.



Beitrag von „fabiosun“ vom 17. November 2022, 17:32

[Fyynn](#) could you try this config.plist?

[config.plist.zip](#)

it is yours with some kext disabled

Beitrag von „Hecatomb“ vom 17. November 2022, 18:29

Moin Fyynn mir fällt auch noch ne andere Möglichkeit bezüglich des crash ein, aktiviere oder deaktiviere mal diese komischer resize Bar gpu option im bios. viel erfolg !!!!

Beitrag von „Fyynn“ vom 17. November 2022, 18:47

[Bob-Schmu](#) wie das denn?

[fabiosun](#) jea with this config its working

[Hecatomb](#) hat leider nichts gebracht

Beitrag von „fabiosun“ vom 17. November 2022, 18:49

[Zitat von Fyynn](#)

fabiosun jea with this config its working

I have disabled BT /WIFI and Ethernet kexts

I think you have to update it (I do not if your ethernet is well supported in Ventura OS)

Beitrag von „Fyynn“ vom 17. November 2022, 18:50

actually already have the lastest version

Beitrag von „fabiosun“ vom 17. November 2022, 18:54

[Zitat von Fyynn](#)

actually already have the latest version

for airport and Ventura I think you need the alpha one

<https://github.com/OpenIntelWireless/itlwm/releases>

I would try for now to enable only the ethernet kext and see if the problem happens again

Beitrag von „Hecatomb“ vom 17. November 2022, 18:59

Hat sich schon erledigt mit der gpu... ist also ethernet...

Beitrag von „Fyynn“ vom 17. November 2022, 19:35

ok with the new kext file everything works without crashing.

Thank you for that, I have no longer thought of this the it is still the old version.

However, I still have the problem with my wireless keyboard, I can't connect it but for example my box connecting without my problems

you ever heard about this?

Beitrag von „fabiosun“ vom 17. November 2022, 19:45

[Zitat von Fyynn](#)

However, I still have the problem with my wireless keyboard, I can't connect it but for example my box connecting without my problems

you ever heard about this?

sorry I do not understand well this part

Beitrag von „Fyynnn“ vom 17. November 2022, 19:49

sorry for my bad english.

I mean that I can't connect my wireless keyboard via Bluetooth.

But my Bluetooth speaker works well.

Hope you can understand it now

Beitrag von „fabiosun“ vom 17. November 2022, 19:51

no no it is not your English

so it is a BT

have you mapped your internal BT (if used USB port as 255?)

No much experience in this subject, I have a Fenvi and my system does not need to map USB

Beitrag von „Fyynnn“ vom 17. November 2022, 19:54

yea I have done everything an under Monterey everything has worked. Only since Ventura it doesn't work anymore

Beitrag von „ozw00d“ vom 18. November 2022, 08:19

[Fynn](#) it seems your usb Ports aren't correctly mapped.

read about the ssdt usb solution. It works much finer than the old usbkext method.

i have seen this also with my board and many others.

It works also with the kext, but apple is working on the way how usb is working on a Mac on each new version.

I don't really understand why apple is changing everytime things on usb.

could you please attach an ioreg dump and your usbkext?

I could bet that the problem is an usb related thingy.

Beitrag von „Fyynn“ vom 18. November 2022, 08:26

Hmm eigentlich sollten sie das weil in Monterey hat es geklappt, aber ich werde mich nochmal erkundigen.

Was halt fehlt ist, wenn ich mich verbinden will taucht normalerweise ein kleines Fenster auf mit einem Code, den ich auch der Tastatur eingeben muss, dass sie sich verbindet. Dieser Taucht in Ventura nicht auf.

Was genau meinst du mit ioreg dump? (Sorry für die dumme frage aber sagt mit gerade nichts)

USB-Kext nehme ich an von der, die ich erstellt habe beim mapping?

LG 😊