Fire wire port lost after multiple reboot

Beitrag von „OMWO" vom 28. Januar 2012, 00:35

Hi Schneelöwe,

I read more and more comment from people who lost their FireWire port after an Update.
I do have some Back up... But quite old... 2009...

Or, is there someone on the web who found a patch to repair the bad action of the update?

A guy wrote: *Good to hear you got it sorted but not good if 10.6.8 has got some sort of fatal firewire flaw, although as Robert's got an Ultralite that works under 10.6.8 it seems not - I'm interested as I've got an UL too and was thinking of updating. Received wisdom says it's better to use Combo updater rather than the one Apple pushes. Oh, and repair permissions.*
Anyone else having success/problems with FW and this OS version?

*Tt*Try downloading and installing the Combo installer, *http://support.apple.com/kb/DL1399*

I am still interested with your suggestions...