`Erledigt` Hp 8470p Fixes!

Beitrag von „pole“ vom 14. Januar 2018, 22:34

Hi!

I have an 8470p with Amd 7570m graphics card on latest High Sierra 10.13.2 (17C205).

Fully functional, except:

-my cpu is working on base clock(2.7 Ghz), can't get the turbo boost.(~3.5 Ghz 4core 45w) (wrong cfg, I think)
-no handoff (My BT controller isn't supported I guess, but I can pair with my iPhone.)
Broadcom 20702A3
Vendor ID: 0x0A5C
Product ID:0x21E1

(AR9285 wifi)

-the config.plist file has a little bit of messed, because when I paste the EFI folder to the volume and install the kexts then i restarting i get some error.
-DSDT/SSDT file is generated with "old" PBI-CE. (But i created SSDT with ssdtPRGen.sh)
-wrong SMBIOS ? -I'm using MacBookPro10,2, but 3740qm was only in MacBookPro10,1.
-Clover version 4289. (I created bootable usb with Unibeast, and installed clover only in UEFI and ESP)

I would like to:
-right way working cfg.(How to do that? - yeah, I know, use clover conf. or Plist editor, but what/how for best)
-I can be installing kexts to /Library/Extensions without any issues and not only read kexts from /Volume/EFI/CLover/Kext/Other or running.
-which kexts are need it, exactly?

I attached some files are you need it, tell me if need more information.
I don't know, can i write in English I didn't find a policy.

Thank You!