Neuer Hackintosh nach 6 Jahren - passt das für ne VIDEO Workstation ?

Beitrag von „MPC561" vom 16. Januar 2021, 15:00

[hannibal1969](#)

I think most of us know this possibility, nevertheless thx. I know it as Morpheus Mod.

See for instance here a description for modding and undervolting a Vega: [Click](#)

Btw. me also knows the problem of the reset of the injected parameters in RAM with original ones in BIOS ROM. But me was to nervous to flash a modded BIOS with a new powerplay table. 🙂

At the end my conclusion was, that this happened when you undervolt to much or changed the HBM3 (or was it 2?)in a not correct way.

So it may happen that all Test under load were successful but anyhow sometimes under certain simple short peak loads the card reseted. It seemed that this problems were linked with clock changes the card internaly does with high clock gradients. This clock changes also may happen under full load of the card (although the gradients are then not so high), as the card then gets hot -- HW reduces clock -- card temperature goes down -- HW increased clock -- and again and again.

I solved it by more conservative undevolting. Then this problems (and the linked Fan problems) didnt appear anymore. (At least until I removed my Vega 56 because a exploding AIO Watercooling killed her ...)

Greets,

Joerg