[Sammelthread] MacOS Monterey 12.x DEV-Beta Erfahrungen

Beitrag von „fabiosun“ vom 7. Oktober 2021, 08:55

Since beta 6, I sporadically have this error in the verbose.

It would appear to be related to the Intel 211 internal cards of my MSI TRX40 Pro.

These are active in the BIOS but are not used (I have not installed the necessary kext in the Kext folder of OpenCore)

Does it happen to others?

With previous betas or with Big Sur it didn't happen

After attached coloured screen my monitors go to a black screen with signal