Fire wire port lost after multiple reboot

Beitrag von „OMWO" vom 28. Januar 2012, 00:04

Could some FireWire expert take a look to this.
In fact I search on the web and some guy got the exactly same problem like me... After an update....

Please, what this ou: http://forum.ableton.com/viewtopic.php?f=1&t=166293

This guy wrote: it was the update to blame.
i did a system restore using time machine, and all works just like before.

i heard from some others, too, that the 10.6.8 update fucked up various shit...

Can someone tell me what he really did?