Fire wire port lost after multiple reboot

Beitrag von „OMWO" vom 4. Februar 2012, 18:48

Hi again,,,

In case someone want to know the issue, After a lot of trying retro-grade Kext for FireWire, etc...

I decided to install the combo 1.6.8.v1.1 something like that and I deleted the AppleHET.kext

And now it works.

Thanks to the great support I got from this forum.

But in particular, thanks a LOT to Griven.

Francois