Erledigt Lenovo T420 - macOS Installation

Beitrag von „No.Trace" vom 15. Februar 2019, 16:07

Ich habe das hier noch in einer anderen Anleitung gefunden. Das versuche ich auch mal.

Code

1. Some users have reported random freezes where the system continues to run but the user interface becomes unresponsive. This problem occurs on many different platforms under High Sierra and is not specific to the X220. Only some X220 units are affected and we have not been able to reproduce the problem on our test units. We believe the problem may have something to do with the graphics framework and shared system memory. Here are a few things to try if you encounter this problem:
2. Update to macOS 10.13.4 or later
3. Press F1 at startup and go to Advanced > System Agent (SA) configuration > Graphics Configuration
4. Set DVMT Pre-Allocated to 128MB
5. Set DVMT Total Gfx Mem to MAX
6. If you have two RAM modules installed, try removing one and see if the problem still occurs. It may be that just one module that is the source of the trouble.
7. If you have less than 8GB of RAM, adding additional RAM may help
8. Try adjusting hardware acceleration settings, if possible, for applications that are running when the freezes occur (such as Chrome)