`Umsetzung prüfen` # Ozmosis mit macOS Catalina 10.15 – OZ167X-XMAX (extended)

Beitrag von „nokiachangzhi" vom 20. März 2020, 09:00

> [Zitat von kuckkuck](#)
>
> Which files are on your EFI Partition?
>
> On first look I immediately see that
>
> 1. your defaults.plist is injected as a PE32 image section, not as Raw, this leads to invalid DOS signatures as well
>
> 2. your defaults.plist itself is broken and corrupted
>
> 3. your defaults.plist contains an incompatible SMBios.
>
> So I wonder, where is this OzmosisDefaults.ffs from that you are using? I wonder how it is even possible to create something like this🤔
>
> Alles anzeigen

Hi

The files on my EFI partition have been packaged and uploaded in the attachment.

1. My ozmosisdefaults.plist is edited with Ozmosis configurator, then converted to ozmosisdefaults.ffs with "kext2ffs", and finally inserted into ROM with uefitool. Is this a problem in which link?

2. In fact, when I put defaults.plist in the EFI folder, it doesn't work, and occasionally it will fail to start.

3. As for the selection of SMBIOS, I have tried both models 15.1 and 14.2. There is no difference. They both work normally after startup. occasionally, they are stuck and unable to start. I chose 15.1 because I saw in Ozmosis configurator that 15.1 is closer to the actual configuration of my computer.

So, how exactly did the problem arise? How can I get the correct ozmosisdefaults.ffs and defaults.plist?