`Umsetzung prüfen` Ozmosis mit macOS Catalina 10.15 – OZ167X-XMAX (extended)

Beitrag von „kuckkuck" vom 20. März 2020, 11:47

First of all Ozmosis Configurator is broken and not up to date, it provides old values and injects properties that don't exist. Don't use Ozmosis Configurator at this point in time. Please edit you defaults.plist by hand according to the information found on this forum.

Did you edit and convert the defaults.plist that can be found in your ROM yourself? I don't get how this kind of corruption can happen, there are parts of the Ozmosis.efi binary and different picture binaries inside of your defaults.ffs! This is beyond my imagination tbh...

Also your kext2ffs version seems to work incorrectly or you are not using it properly. Please try a different version of kext2ffs, there's a download thread in this forum.