Lenovo Thinkpad T530

Beitrag von „PDM" vom 24. Oktober 2020, 13:13

5T33Z0: "before upgrading to an i7" can you elaborate on that? Because my X43-NUC is not longer working at the moment, I may need to beef-up the T530.

Hey, thanks for the power management, will try it immediately. Maybe the 900MHz was the issue during boot. But I remember now that this was mentioned in the past (I think by you), but I totally forgot.

[update]

OK, it booted! Stupid question, how do I verify that it's working?