Erledigt AQUANTIA 10 Gigabit Lan Port "Tot"

Beitrag von „fabiosun“ vom 21. Dezember 2022, 14:26

alecxx

For aquantia and AMD chipset are available different patches

it is working now perfectly






Mac Pro
Hardware
ATA
Apple Pay
Audio
Bluetooth
Camera
Card Reader
Controller
Diagnostics
Disc Burning
Ethernet
Fibre Channel
Firewire
Graphics/Displays
Memory
NVMExpress
PCI
Parallel SCSI
Power
Printers
SAS
SATA
SPI
Storage
Thunderbolt/USB4
USB
Network
Firewall
Locations
Volumes
WWAN
Wi-Fi
Software
Accessibility
Applications
Developer
Disabled Software
Ethernet Devices
Bus
Aquantia AQC107
PCI
Intel(R) Ethernet Controller I211 Copper (IGB)
PCI
Intel(R) Ethernet Controller I211 Copper (IGB)
PCI
Aquantia AQC107:
Bus: PCI
Vendor ID: 0x1d6a
Device ID: 0x07b1
Subsystem Vendor ID: 0x1462
Subsystem ID: 0x0912
Revision ID: 0x0002
PCIe Link Speed: 8.0 GT/s
PCIe Link Width: x4
Firmware Version: 3.1.81
Driver: com.apple.driver.AppleEthernetAquantiaAqtion
BSD Device Name: en0
MAC Address:
AVB Support: Yes
Maximum Link Speed: 10 Gb/s