NVMe Probleme in Big Sur

Beitrag von „Jas9a" vom 12. Februar 2024, 14:39

Hey,

I'm trying to run macOS Big Sur on my HP Pavilion x360

14 cd0601ng (It's my first time doing this). Everything

Worked fine until I tried to install macOS after entering

Disk Utility I looked for my lexar nm610pro NVMe drive

just to find out it's not showing up in Disk Utility. So

my question is the Lexar nm61 0pro not supported

or am I missing any file in my EFI folder. Here is the

my EFI as attachment below. Can someone please help me.

CPU: Intel i3 8130u

GPU: Intel UHD 620

RAM: 4gb 2400mhz

SSD: Lexar NM610pro 500gb

Model: HP Pavilion x360 14 cd0601ng