Hot plug ICH10 patch does not work (An error occurred while preparing the installation)

Beitrag von „v1ta" vom 4. Januar 2023, 04:53

Hello! I'm trying to install Catalina (since the necessary software works on it, and so, and would continue to work in Sierra). A year ago, I managed to do this, hot plugging worked, I remember copying two kexts AHCIPortInjector and AHCIPort, but not all disks were initialized and eventually the system rebooted. This time nothing helps, including 4 patches in clover.

I have attached the error log. Installation ends with "An error occurred while preparing the installation. Try running this application again."