

panic(cpu 6 caller 0xfffff80009ee996): Kernel trap at 0xfffff8000fdc502, type 14=page fault, registers:

CR0: 0x000000008001003b, CR2: 0x000000000000160, CR3: 0x000000001683f000, CR4: 0x0000000003626e0

RAX: 0x0000000000000000, RBX: 0xfffff936ef1fa30, RCX: 0x0000000000000000, RDX: 0x0000000000000001

RSP: 0xfffffb09fabbbd0, RBP: 0xfffffb09fabbc10, RSI: 0x00000000ffffff, RDI: 0xfffff86b40bdcb0

R8: 0x000000000000000e, R9: 0x0000000000000001, R10: 0xfffff936ef71a90, R11: 0xfffff8000f76710

R12: 0xfffff86b257eb80, R13: 0xfffff86b40bdcb0, R14: 0xfffff86b40bdcb0, R15: 0xfffff86af2c47a0

RFL: 0x000000000010246, RIP: 0xfffff8000fdc502, CS: 0x0000000000000008, SS: 0x0000000000000010

Fault CR2: 0x000000000000160, Error code: 0x0000000000000000, Fault CPU: 0x6, PL: 0, VF: 1

Backtrace (CPU 6), Frame : Return Address

0xfffffb09fabbb5f0 : 0xfffff80008bc65d mach_kernel : _handle_debugger_trap + 0x3dd

0xfffffb09fabbb640 : 0xfffff80009fdbba3 mach_kernel : _kdp_i386_trap + 0x143

0xfffffb09fabbb680 : 0xfffff80009ee5ca mach_kernel : _kernel_trap + 0x55a

0xfffffb09fabbb6d0 : 0xfffff8000861a2f mach_kernel : _return_from_trap + 0xff

0xfffffb09fabbb6f0 : 0xfffff80008bbefd mach_kernel : _DebuggerTrapWithState + 0xad

0xfffffb09fabbb810 : 0xfffff80008bc1e8 mach_kernel : _panic_trap_to_debugger + 0x268

0xfffffb09fabbb880 : 0xfffff80010ba3ca mach_kernel : _panic + 0x54

0xfffffb09fabbb8f0 : 0xfffff80009ee996 mach_kernel : _sync_iss_to_iks + 0x2c6

0xfffffb09fabba70 : 0xfffff80009ee67d mach_kernel : _kernel_trap + 0x60d

0xfffffb09fabbac0 : 0xfffff8000861a2f mach_kernel : _return_from_trap + 0xff

0xfffffb09fabbae0 : 0xfffff8000fdc502 mach_kernel :

__ZN15IORegistryEntry11setPropertyEPK8OSSymbolP8OSObject + 0xc2

0xfffffb09fabbc10 : 0xfffff800100d7bf mach_kernel :

__ZN15IOPMPowerSource12updateStatusEv + 0xdf

0xfffffb09fabbc40 : 0xfffff80047b5bef com.superhai.driver.VoodooBattery :

__ZN19VoodooBatteryDevice9dynstatusEv + 0x549

0xfffffb09fabbc0 : 0xfffff80047b5d22 com.superhai.driver.VoodooBattery :

__ZN19VoodooBatteryDevice6updateEb + 0x100

0xfffffb09fabbc0 : 0xfffff80047b5d8b com.superhai.driver.VoodooBattery :

__ZN19VoodooBatteryDevice7messageEjP9IOServicePv + 0x2b

0xfffffb09fabbcf0 : 0xfffff80047b3e85 com.superhai.driver.VoodooBattery :

__ZN23VoodooBatteryController4pollEv + 0x35

0xfffffb09fabbd10 : 0xfffff80047b5cb0 com.superhai.driver.VoodooBattery :

__ZN19VoodooBatteryDevice6updateEb + 0x8e

0xfffffb09fabbd40 : 0xfffff80047b5d8b com.superhai.driver.VoodooBattery :

__ZN19VoodooBatteryDevice7messageEjP9IOServicePv + 0x2b

0xfffffb09fabbd50 : 0xfffff8000fe5b43 mach_kernel :

__ZN26_IOServiceInterestNotifier4waitEv + 0xe3

0xfffffb09fabbd70 : 0xfffff8000fdd589 mach_kernel :

__ZNK15IORegistryEntry15applyToChildrenEPFvPS_PvES1_PK15IORegistryPlane + 0xa9

0xffffffffb09fabbd0 : 0xffffffff8000fe4f03 mach_kernel :
__ZN9IOService17applyToInterestedEPK8OSSymbolPFvP8OSObjectPvES5_ + 0x33
0xffffffffb09fabbd0 : 0xffffffff8000fe4d92 mach_kernel :
__ZN9IOService14messageClientsEjPvm + 0x42
0xffffffffb09fabbe10 : 0xffffffff8001877fec com.apple.driver.AppleACPIPlatform :
__ZN23AppleACPIPlatformExpert18dispatchACPINotifyEP9IOServicej + 0x28
0xffffffffb09fabbe30 : 0xffffffff80018a5883 com.apple.driver.AppleACPIPlatform :
_AcpiEvNotifyDispatch + 0x2a
0xffffffffb09fabbe50 : 0xffffffff800188f8b8 com.apple.driver.AppleACPIPlatform :
_AcpiOsThreadCallDispatch + 0x1d
0xffffffffb09fabbe80 : 0xffffffff8000900ff5 mach_kernel : _thread_call_delayed_timer + 0x4a5
0xffffffffb09fabbef0 : 0xffffffff8000901f04 mach_kernel : _thread_call_delayed_timer + 0x13b4
0xffffffffb09fabbfa0 : 0xffffffff800086113e mach_kernel : _call_continuation + 0x2e

Kernel Extensions in backtrace:

com.apple.driver.AppleACPIPlatform(6.1)[F121AE55-819F-3B54-965F-48746DEDF38]@0xffffffff8001872000->0xffffffff80018e8fff
dependency: com.apple.driver.AppleSMC(3.1.9)[4BCEDBBE-203B-3201-9ABB-E85362982273]@0xffffffff8001e6b000->0xffffffff8001e83fff
dependency: com.apple.iokit.IOACPIFamily(1.4)[F42E4E8D-BBE9-37B7-A3A4-9D9641BBB848]@0xffffffff8002c9b000->0xffffffff8002c9cfff
dependency: com.apple.iokit.IOPCIFamily(2.9)[18E1EFFB-84A7-3440-B547-E789CDDF154C]@0xffffffff80031df000->0xffffffff8003206fff
com.superhai.driver.VoodooBattery(1.3.3)[B3C00758-6288-BA5F-E7A3-7AADAEB48DAC]@0xffffffff80047b3000->0xffffffff80047c3fff
dependency: com.apple.iokit.IOACPIFamily(1.4)[F42E4E8D-BBE9-37B7-A3A4-9D9641BBB848]@0xffffffff8002c9b000->0xffffffff8002c9cfff

Process name corresponding to current thread: kernel_task
Boot args: keepsyms=1 alcid=28 vsmcgen=1 shikigva=80

Mac OS version:
20A5384c

Kernel version:
Darwin Kernel Version 20.1.0: Thu Sep 24 20:22:06 PDT 2020; root:xnu-7195.40.89.100.3~1/RELEASE_X86_64
Kernel UUID: F53CBFCA-438C-30C2-BFD7-5D0588C5CD5F
KernelCache slide: 0x000000000600000
KernelCache base: 0xffffffff8000800000
Kernel slide: 0x000000000610000
Kernel text base: 0xffffffff8000810000
__HIB text base: 0xffffffff8000700000
System model name: MacBookPro15,2 (Mac-827FB448E656EC26)
System shutdown begun: NO
Panic diag file available: YES (0x0)
Hibernation exit count: 0

System uptime in nanoseconds: 1289317516711

Last Sleep: absolute base_tsc base_nano
Uptime : 0x0000012c31500854
Sleep : 0x000000ae763e2d30 0x00000003c9f8025c 0x0000000000000000
Wake : 0x000000ae7d9ab4fa 0x00000001be7817a6 0x000000ae78b67fa7