

Erledigt

I did it again! mein 2. Hackintosh

Beitrag von „@Laire“ vom 21. Februar 2014, 05:01

-> Mittlerweile habe ich aus meiner SSD und HDD ein Fusion Drive erstellt welches sehr gut funktioniert.

Eine Sache stört noch:

Immer wenn ich den Rechner neustarte kommt am Anfang beim Ende des Ladezykluses (Schreibtisch - Dock) eine "ihr computer wurde aufgrund eines problems neu gestartet" Meldung mit "Ignorieren" oder "Bericht"

Der weitere Betrieb des Mac ist aber problemlos er arbeitet zügig und ohne ein murren

Fehlerbericht:

XX

Anonymous UUID:

Fri Feb 21 04:43:10 2014

panic(cpu 1 caller 0xfffff80002dc19e): Kernel trap at 0xfffff80002d0b17, type 14=page fault, registers:

CR0: 0x000000008001003b, CR2: 0x0000000000000008, CR3: 0x000000000868b000, CR4: 0x000000000001606e0

RAX: 0xa0d4d80c3caf00ab, RBX: 0xfffff80d6be2000, RCX: 0x00000000002a3c0c, RDX: 0x0000000000000000

RSP: 0xfffff80f4adbe30, RBP: 0xfffff80f4adbe30, RSI: 0x0000000000000002, RDI: 0x0000000000000000

R8: 0x0000000000000001, R9: 0x00000000cccccccd, R10: 0xfffff80008d15f0, R11: 0x0000000000000041

R12: 0xfffff80d6be2000, R13: 0xfffff8018596300, R14: 0xfffff8016e51600, R15: 0xfffff80d6be2000

RFL: 0x0000000000010282, RIP: 0xfffff80002d0b17, CS: 0x0000000000000008, SS: 0x0000000000000000

Fault CR2: 0x0000000000000008, Error code: 0x0000000000000000, Fault CPU: 0x1

Backtrace (CPU 1), Frame : Return Address

0xffffffff80f4adbac0 : 0xffffffff8000222f69
0xffffffff80f4adbb40 : 0xffffffff80002dc19e
0xffffffff80f4adbd10 : 0xffffffff80002f3606
0xffffffff80f4adbd30 : 0xffffffff80002d0b17
0xffffffff80f4adbe30 : 0xffffffff7f80b67f50
0xffffffff80f4adbe50 : 0xffffffff7f80b69b77
0xffffffff80f4adbea0 : 0xffffffff800069259a
0xffffffff80f4adbf30 : 0xffffffff800068e119
0xffffffff80f4adbf70 : 0xffffffff8000693093
0xffffffff80f4adbf0 : 0xffffffff80002d6aa7

Kernel Extensions in backtrace:

org.voodoo.driver.VoodooHDA(2.7.2)[0207F02E-0356-8F6C-6415-61A9334E702C]@0xffffffff7f80b66000->0xffffffff7f80b86fff

dependency: com.apple.iokit.IOAudioFamily(1.9.4fc11)[5077FB4F-0903-3D79-8280-5B2341E93BF3]@0xffffffff7f80b2f000

dependency: com.apple.iokit.IOPCIFamily(2.8)[447B4896-16FF-3616-95A2-1C516B2A1498]@0xffffffff7f808ba000

BSD process name corresponding to current thread: kernel_task

Boot args: slide=0

Mac OS version:

13B42

Kernel version:

Darwin Kernel Version 13.0.0: Thu Sep 19 22:22:27 PDT 2013; root:xnu-2422.1.72~6/RELEASE_X86_64

Kernel UUID: 1D9369E3-D0A5-31B6-8D16-BFFBBB390393

System model name: MacPro3,1 (Mac-F42C88C8)

System uptime in nanoseconds: 3762175277

last loaded kext at 3744134234: com.apple.iokit.IONDRVSupport 2.3.6 (addr 0xffffffff7f81128000, size 65536)

loaded kexts:

org.voodoo.driver.VoodooHDA 2.7.2

com.insan*****c.ALXEthernet 1.0.2
org.netkas.FakeSMC 1.0.0d1
com.apple.AMDRadeonX4000 1.1.4
com.apple.driver.ACPI_SMC_PlatformPlugin 1.0.0
com.apple.kext.AMD7000Controller 1.1.4
com.apple.driver.AppleLPC 1.7.0
com.apple.iokit.IOUserEthernet 1.0.0d1
com.apple.Dont_Steal_Mac_OS_X 7.0.0
com.apple.driver.AppleHWAccess 1
com.apple.driver.AppleIntelFramebufferCapri 8.1.8
com.apple.driver.CoreStorageFsc 380
com.apple.iokit.SCSITaskUserClient 3.6.0
com.apple.driver.AppleFileSystemDriver 3.0.1
com.apple.AppleFSCompression.AppleFSCompressionTypeDataless 1.0.0d1
com.apple.AppleFSCompression.AppleFSCompressionTypeZlib 1.0.0d1
com.apple.BootCache 35
com.apple.driver.XsanFilter 404
com.apple.iokit.IOAHCIBlockStorage 2.4.0
com.apple.driver.AppleUSBHub 650.4.4
com.apple.driver.AppleFWOHCI 4.9.9
com.apple.driver.AppleUSBXHCI 650.4.3
com.apple.driver.AppleAHCIPort 2.9.5
com.apple.driver.AppleUSBECI 650.4.1
com.apple.driver.AppleRTC 2.0
com.apple.driver.AppleACPIButtons 2.0
com.apple.driver.AppleHPET 1.8
com.apple.driver.AppleSMBIOS 2.0
com.apple.driver.AppleAPIC 1.7
com.apple.driver.AppleIntelCPUPowerManagementClient 216.0.0
com.apple.nke.applicationfirewall 153
com.apple.security.quarantine 3
com.apple.driver.AppleIntelCPUPowerManagement 216.0.0
com.apple.iokit.IONDRVSupport 2.3.6
com.apple.iokit.IOAudioFamily 1.9.4fc11
com.apple.kext.OSvKernDSPLib 1.14
com.apple.iokit.IOAcceleratorFamily 98.7.1
com.apple.iokit.IOFireWireIP 2.2.5
com.apple.driver.AppleHDAController 2.5.3fc1
com.apple.iokit.IOHDAFamily 2.5.3fc1
com.apple.driver.IOPlatformPluginLegacy 1.0.0
com.apple.driver.AppleSMBusPCI 1.0.12d1
com.apple.kext.AMDSupport 1.1.4
com.apple.driver.IOPlatformPluginFamily 5.5.1d27

com.apple.iokit.IOSurface 91
com.apple.iokit.IOBluetoothFamily 4.2.0f6
com.apple.driver.AppleSMC 3.1.6d1
com.apple.iokit.IOAcceleratorFamily2 98.7.1
com.apple.AppleGraphicsDeviceControl 3.4.12
com.apple.iokit.IOGraphicsFamily 2.3.6
com.apple.iokit.IOSCSIBlockCommandsDevice 3.6.0
com.apple.iokit.IOUSBMassStorageClass 3.6.0
com.apple.iokit.IOUSBHIDDriver 650.4.4
com.apple.driver.AppleUSBMergeNub 650.4.0
com.apple.driver.AppleUSBComposite 650.4.0
com.apple.iokit.IOSCSIMultimediaCommandsDevice 3.6.0
com.apple.iokit.IOBDStorageFamily 1.7
com.apple.iokit.IODVDStorageFamily 1.7.1
com.apple.iokit.IOCDStorageFamily 1.7.1
com.apple.driver.CoreStorage 380
com.apple.iokit.IOAHCIATAPI 2.6.0
com.apple.iokit.IOSCSIArchitectureModelFamily 3.6.0
com.apple.iokit.IOUSBUserClient 650.4.4
com.apple.iokit.IOFireWireFamily 4.5.5
com.apple.iokit.IONetworkingFamily 3.2
com.apple.driver.AppleEFINVRAM 2.0
com.apple.iokit.IOAHCIFamily 2.6.0
com.apple.iokit.IOUSBFamily 650.4.4
com.apple.driver.AppleEFIRuntime 2.0
com.apple.iokit.IOHIDFamily 2.0.0
com.apple.security.sandbox 278.10
com.apple.kext.AppleMatch 1.0.0d1
com.apple.security.TMSafetyNet 7
com.apple.driver.AppleKeyStore 2
com.apple.driver.DiskImages 371.1
com.apple.iokit.IOStorageFamily 1.9
com.apple.iokit.IOReportFamily 21
com.apple.driver.AppleFDEKeyStore 28.30
com.apple.driver.AppleACPIPlatform 2.0
com.apple.iokit.IOPCIFamily 2.8
com.apple.iokit.IOACPIFamily 1.4
com.apple.kec.corecrypto 1.0
com.apple.kec.pthread 1

Model: MacPro3,1, BootROM MP31.006C.B05, 4 processors, Intel Core i5, 3.4 GHz, 8 GB, SMC 1.30f3

Graphics: AMD Radeon HD 7950, AMD Radeon HD 7950, PCIe, 3072 MB

Memory Module: BANK 3/ChannelB-DIMM1, 4 GB, DDR3, 1600 MHz, G Skill Intl, F3-12800CL9-

4GBSR2

Memory Module: BANK 1/ChannelA-DIMM1, 4 GB, DDR3, 1600 MHz, G Skill Intl, F3-12800CL9-4GBSR2

Network Service: Ethernet, Ethernet, en0

Serial ATA Device: WDC WD10EZEX-00ZF5A0, 1 TB

Serial ATA Device: Samsung SSD 840 Series, 120,03 GB

Serial ATA Device: PLEXTOR DVDR PX-891SA

Serial ATA Device: ST3640323AS, 640,14 GB

USB Device: Hub

USB Device: Hub

USB Device: USB2.0 Hub

USB Device: USB to ATA/ATAPI Bridge

USB Device: USB Receiver

Thunderbolt Bus:

XX



Vielleicht fällt einem von Euch was ein dazu

LG