

Erledigt

Aller Anfang ist Schwer

Beitrag von „apatchenpub“ vom 11. November 2015, 22:55

eigentlich bedarf es nur ein paar Änderungen in der IONetworkingFamily.kext, habe hier mal was gefunden:

Code

1. To enable the first LAN port (which, of the two available ports, is the one further away from the keyboard/mouse ports), the best approach is, on every OS update, to edit the file
`/System/Library/Extensions/IONetworkingFamily.kext/Contents/PlugIns/AppleYukon2.kext/Contents/Info`
find the key Yukon-88E8053, and replacing it with the key name Yukon-88E8056; in the values associated to this key, update also:
- 2.
- 3.
4. The key IOPCIPrimaryMatch, which has value 0x436211ab should have instead value 0x436411ab
5. The key Model should be also edited to have value Yukon Gigabit Adapter 88E8056 Singleport Copper SA

vielleicht hilft dir das weiter. Dein Board hat ja leider nicht denselben LAN-Chip wie meines