

# USB Patch für GA-Z97X-UD3H - El Capitan

Beitrag von „al6042“ vom 16. Januar 2016, 12:17

Oh...

Meine USB2.0 Schnittstellen liefern, je nach angeschlossenem Gerät, folgende Werte:

The image shows two screenshots of the macOS System Information utility, specifically the USB section. The left screenshot shows the 'HD Webcam C525' selected, with its 'Speed' highlighted in green as 'Up to 480 Mb/sec'. The right screenshot shows the 'USB Receiver' selected, with its 'Speed' highlighted in green as 'Up to 12 Mb/sec'. Both screenshots show the 'USB Device Tree' on the left and the device's technical specifications on the right.

**HD Webcam C525:**

Product ID:	0x0826
Vendor ID:	0x046d (Logitech Inc.)
Version:	0.10
Serial Number:	F018C525
Speed:	Up to 480 Mb/sec
Location ID:	0x1c194000 / 4
Current Available (mA):	1000
Current Required (mA):	500
Extra Operating Current (mA):	0

**USB Receiver:**

Product ID:	0xc52b
Vendor ID:	0x046d (Logitech Inc.)
Version:	12.03
Speed:	Up to 12 Mb/sec
Manufacturer:	Logitech
Location ID:	0x1c164000 / 5
Current Available (mA):	1000
Current Required (mA):	98
Extra Operating Current (mA):	0