

Erledigt

Handoff aktivieren

Beitrag von „luxus13“ vom 21. Februar 2016, 00:25

Hallo,
mein MacPro 3.1 läuft sehr gut bis auf eine Kleinigkeit.
Handoff geht nicht, Airdrop geht.
Fehler für mich die Mac-Board-ID.

```
--- Initiating system compatibility check ---  
--- Hardware/OS checks ---  
Verifying Continuity status... OK. OS X reports Continuity as active  
Verifying Mac model reference... OK. Known compatible Mac Model detected: MacPro3,1  
Verifying Mac board-id... OK. Short board id detected: Mac-Fxxxxxx8  
Verifying OS X version... Warning: This version of Mac OS X (10.11.4) is Experimental! Only  
partially tested on El Capitan  
Verifying Wi-Fi hardware... OK. A Broadcom AirPort card is active, and is using the Continuity  
compatible Brcm4360 kext  
Verifying AWDL status... OK. An AWDL interface is up, Wi-Fi is ready for Continuity  
Verifying Bluetooth hardware... OK. The internal Bluetooth card is active  
Verifying Bluetooth version... OK. Bluetooth 4.0 detected  
Verifying Bluetooth features... OK. Bluetooth features are Continuity compliant  
Verifying Bluetooth firmware... OK. Bluetooth firmware version: v118 c9123  
Verifying Login Item... OK. Login item for Auto Continuity Check is not set.  
--- Modifications check ---  
Verifying OS kext protection... OK. Kext developer mode is not active. This tool can fix this.  
Verifying SIP... Ok. System Integrity Protection is already disabled  
Verifying ContinuitySupport... Print: Entry, "Mac-Fxxxxxx8:ContinuitySupport", Does Not Exist  
NOT OK. Unknown state. Your Mac might not be compatible.  
Verifying kexts readability... OK. Wi-Fi and Bluetooth kexts were found and could be read  
Verifying Wi-Fi whitelist status... OK. The whitelist is correctly patched with your board-id  
Verifying BT4 dongles compatibility... OK. Compatibility with BT4 USB dongles is not enabled,  
this tool can fix this if a dongle is plugged in  
Verifying old Wi-Fi kext presence... OK. Legacy Wi-Fi driver Brcm4331 was already removed  
Verifying legacy Wi-Fi card patch... OK. The patch is already done. Old Broadcom Wi-Fi cards  
may work.  
--- Modifications check ---
```

Die xxxxxx sind von mir gesetzt worden.

Laut Systembericht:

Bluetooth Low Energy wird unterstützt: Ja

Handoff wird unterstützt: Ja

Instant Hotspot unterstützt: Ja

AirDrop: Supported

Also die Voraussetzungen sind gegeben.

Laut Google sollte MacPro 3.1 nicht das Problem sein, würde aber auch eine andere Systemdefinition nehmen wenn nötig.

Hat jemand eine Idee wie ich Handoff zum laufen bringe?

VG