

Erledigt

DSDT fix Z87MX-D3H (OZ167X)

Beitrag von „nikoZ“ vom 28. Februar 2016, 10:29

I saw that EC problem, on the apple forums. It solved by a script. Not a problem anymore. It looks like multiplier wasn't changing and i executed pike's script like this

Code

1. 0 = no workarounds
- 2.
- 3.
4. 1 = inject extra (turbo) P-State at the top with maximum (turbo) frequency + 1 MHz
- 5.
- 6.
7. 2 = inject extra P-States at the bottom
- 8.
- 9.
10. 3 = both

I used `./ssdtPRGen.sh -w 3` to force multiplier to change.