

Erledigt

DSDT fix Z87MX-D3H (OZ167X)

Beitrag von „Huberer“ vom 28. Februar 2016, 13:34

Could be a bug could also be possible of the in ozmosis integrated kexts. I've no clue. Do you have an opportunity to measure the power consumption of your hackintosh? With this you can be sure if speedstep is working properly and if the power consumption is down when the power gadget shows the cpu idling. There you can be sure that everything is working like it should. In my opinion I would leave it like it is. If you try to work with different kexts (like fakesmc or similar) you risk of bricking your system and have to reinstall everything again.