

Erledigt

DSDT fix Z87MX-D3H (OZ167X)

Beitrag von „Adnarel“ vom 28. Februar 2016, 13:46

Not shure if it is solved jet, that USB looses Power while sleep.

I think the ErP Setting in the BIOS (Energy pane) could be a possibility why the "disk is not ejected properly".

I have had this issue and activating ErP solved it.

But I still running Yosemite and it is only a glimpse of an idea.