

## Beitrag von "locus" vom 12. Juni 2016, 10:53

The problem was that I thought I had s	et:
--	-----

sudo nvram 1F8E0C02-58A9-4E34-AE22-2B63745FA101:DisableNvidiaInjection=%01

It turned out that it was all in my mind, after I set DisableNvidiaInjection to true and a reboot my DisplayPort worked.

Sorry for the confusion and thanks for the suggestions!