

Erledigt

USB-Bluetooth-Stick für Handoff

Beitrag von „PandaX“ vom 13. Juli 2016, 22:41

Nach dem Tool anscheinend ja doch 😊

Code

1. --- Hardware/OS checks ---
- 2.
- 3.
4. Verifying Continuity status... OK. OS X reports Continuity as active
- 5.
- 6.
7. Verifying Mac model reference... OK. Known compatible Mac Model detected: iMac14,2
- 8.
- 9.
10. Verifying Mac board-id... OK. Long board id detected: Mac-27ADBB7B4CEE8E61
- 11.
- 12.
13. Verifying OS X version... Warning: This version of Mac OS X (10.11.5) is Experimental!
Only partially tested on El Capitan
- 14.
- 15.
16. Verifying Wi-Fi hardware... OK. A Broadcom AirPort card is active, and is using the
Continuity compatible Brcm4360 kext
- 17.
- 18.
19. Verifying AWDL status... OK. An AWDL interface is up, Wi-Fi is ready for Continuity
- 20.
- 21.
22. Verifying Bluetooth hardware... WARNING. No Bluetooth controller references were found
in the PRAM, dongles can't be detected.
- 23.
- 24.
25. Verifying Bluetooth version... OK. Bluetooth 4.0 detected
- 26.
- 27.
28. Verifying Bluetooth features... OK. Bluetooth features are Continuity compliant
- 29.
- 30.
31. Verifying Bluetooth firmware... OK. Bluetooth firmware version: v14 c5578
- 32.
- 33.
34. Verifying Login Item... OK. Login item for Auto Continuity Check is not set.

- 35.
- 36.
37. --- Modifications check ---
- 38.
- 39.
40. Verifying OS kext protection... OK. Kext developer mode is already active
- 41.
- 42.
43. Verifying SIP... Ok. System Integrity Protection is already disabled
- 44.
- 45.
46. Verifying ContinuitySupport... Print: Entry, ":Mac-27ADBB7B4CEE8E61:ContinuitySupport", Does Not Exist
- 47.
- 48.
49. NOT OK. Unknown state. Your Mac might not be compatible.
- 50.
- 51.
52. Verifying kexts readability... OK. Wi-Fi and Bluetooth kexts were found and could be read
- 53.
- 54.
55. Verifying Wi-Fi whitelist status... OK. The whitelist is correctly patched with your board-id
- 56.
- 57.
58. Verifying BT4 dongles compatibility... OK. Compatibility with BT4 USB dongles is not enabled, this tool can fix this if a dongle is plugged in
- 59.
- 60.
61. Verifying old Wi-Fi kext presence... OK. Legacy Wi-Fi driver Brcm4331 was already removed
- 62.
- 63.
64. Verifying legacy Wi-Fi card patch... OK. The patch is already done. Old Broadcom Wi-Fi cards may work.
- 65.
- 66.
67. --- Modifications check ---

Alles anzeigen