

AppleALC - der dynamische AppleHDA Patcher - immer aktuell

Beitrag von „al6042“ vom 28. August 2016, 12:19

Und hier die aktuellste Version 1.0.13, mit folgenden Änderungen:

- Improved workaround for 10.12 Beta issues
- Fixed PAGE FAULT panic on 10.12 Beta
- Added version information on boot
- Added ALC898 layout-id 11 for MSI GT72S 6QF-065CN by Irving23
- Added Conexant CX20724 layout-id 13 by InsanelyDeepak
- Added Cirrus Logic CS4210 codec support layout-id 13 by InsanelyDeepak
- Added Realtek ALC275 layout-id 13 by InsanelyDeepak
- Added Realtek ALC891 codec support layout-id 13 by InsanelyDeepak
- Added IDT 92HD90BXX layout-id 12 for Dell Latitude E6x20/Dell Precision Mx600 by vusun123
- Added ALC275 layout-id 28 for Sony Vaio by vusun123
- Added ALC298 codec support layout-id 13 by InsanelyDeepak
- Added AD1984A codec support layout-id 11 by MacPeet
- Added revision-id into AD1984A info.plist
- Fixed lock acquisition panic in iokit routines on 10.12 Beta
- **Removed ALC1150 layouts 1-3 to reduce kext size**
- > **ACHTUNG: Für alle User, welche die ALC1150 aktuell mit Layout-ID 1 nutzen... Hier sollte die Layout ID auf 11 gewechselt werden, damit Audio mit dieser Version funktioniert.**

Entweder per Clover Config.plist "Devices" -> "Audio" -> "Inject" oder per DSDT Patch im Bereich "Device (HDEF)" von

Code

1. "layout-id",
2. Buffer (0x04)
3. {
4. 0x01, 0x00, 0x00, 0x00
5. },

auf

Code

1. "layout-id",
2. Buffer (0x04)
3. {
4. 0x0b, 0x00, 0x00, 0x00
5. },

Oder einfach die Version 1.0.14 nutzen... 😊

- Added ALC1150 layout 11 with boosted microphone (built on 7)