

Erledigt

# Hilfe bei Enoch El Captian installation gesucht!

Beitrag von „johnnyXxX“ vom 7. Dezember 2016, 15:23

Jetzt bekomme ich beim Starten und ausführen die ganze Zeit das hier angezeigt. Da ist irgendetwas schief gelaufen. 🤔

```
000134.041155 UHC2052000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000.019412 UHC4053000000: AppleUSBHCI::StopUSBBus: USBSTS.HCHalted did not set as expected: USB
000134.167637 UHC2052000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000134.044165 UHC2052000000: AppleUSBHCI::StopUSBBus: USBSTS.HCHalted did not set as expected: USB
004000
000134.260878 UHC4053000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: U
000000
000134.239885 UHC6056000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000
000134.288278 UHC4053000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000
000134.307885 UHC8058000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000
000134.388888 UHC2052000000: AppleUSBHCI::StopUSBBus: USBSTS.HCHalted did not set as expected: USB
000
000134.603229 UHC8058000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
004000
000134.628886 UHC2052000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000
000134.638768 UHC6056000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000
000134.628298 UHC4053000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000799.738768 UHC8058000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000134.771971 UHC2052000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000.748282 UHC4053000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000134.895569 UHC2052000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000134.771971 UHC2052000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000.979989 UHC6056000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000134.989989 UHC4056000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
004000
000135.989887 UHC4056000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000
000135.102883 UHC4056000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000
000135.138849 UHC2052000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000
000135.288288 UHC2052000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000
000135.248288 UHC8058000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000
000135.354738 UHC4056000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
004000
000135.368138 UHC4056000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000
000135.488379 UHC4056000000: AppleUSBHCI::RestartUSBBus: USBSTS.HCHalted did not set as expected: USB
000000
```