

AppleALC - der dynamische AppleHDA Patcher - immer aktuell

Beitrag von „al6042“ vom 8. Februar 2017, 07:43

Zurück aus dem Krankenstand und direkt die neue Version 1.0.19 gefunden... 😊

Diese umfasst folgende Neuerungen:

- Added ALC269 layout-id 35 for Samsung NP350V5C-S0URU by Mirone
- Added Conexant CX20755 layout-id 3 by Mirone
- Added ALC269VB layout-id 76 for ENZ C16B by jimmy19990
- Added UserPatches.plist for internal testing
- Added ALC269VB layout-id 11 for Dell Precision Workstation T1600 by Mosser
- Recovered Creative CA0132 macOS 10.12 patch due to caused issues
- Maximised zlib resource compression level
- Added stripping of tabs and new lines in resources
- Added ALC236 layout-id 11 Initial support by Jake Lo (forum.osxlatitude)
- Added ALC269VC layout-id 14 for Samsung NT550P7C-S65 with subwoofer 2.1ch by Rockjesus
- Added Laptop Intel Skylake HD530 HDMI audio support (ig-platform-id 0x191B0000)
- Added revision-id 0x100001 into ALC236 info.plist
- Added ALC293 codec support layout-id 28, 29 for Lenovo T460/T560 by tluck
- Added Conexant CX20751_2 HDMI/DisplayPort Output fix by syscl
- Added ALC282 layout-id 29 for Dell Inspiron 3521 by Generation88
- Added ALC293 layout-id 11 for Dell E7450 by Andres ZeroCross
- Update PinConfig data for ALC269 layout-id 27 by Andrey1970
- Added ALC3236 (ALC233) layout-id 29 for Asus X550LDV by Mirone
- Added Conexant CX20722 codec support layout-id 3 by Mirone
- Added Conexant CX20753/4 codec support layout-id 3 by Mirone
- Added Conexant CX8050 codec support layout-id 3 by Mirone
- Added Conexant CX8200 codec support layout-id 3 by Mirone
- Added revision-id 0x100103 for ALC885
- Added ALC269VB layout-id 15 for Dell Optiplex 790 by [@MacPeet](#)
- Allowed building for 10.8 without using 10.8 SDK