

Erledigt

DaTec und seine Erfahrungen zu den X99 Boards Aktuell 03.02.17

Beitrag von „rafamundez“ vom 7. März 2017, 17:52

[Zitat von DaTec](#)

ok please Test this EFI

Hi [@DaTec](#), I just tested this EFI. It looks like there was 2 errors: " ACPI Error: [_SB_.PCI0.SAT1] Namespace lookup failure, AE_NOT_FOUND (20140828/dswload-125 " and " AMFILogTrustedKeysFromNVRam: failed getting NVRAM " in addition to the " Unsynchronized TSC for cpu " error from before.

Then it stalls on the line: " 16384 buffer headers and 10240 cluster IO buffer headers "

I've attached a screenshot below. Let me know what you think! Again, thank you for your help!

