

In Arbeit

# XiaoMI 12,5 Zoll (m3 6Y30|4GB RAM) mit Sierra

Beitrag von „Noir0SX“ vom 3. April 2017, 17:22

Na dann mal die Lösung ohne KP 😊

KernelToPatch

```
Find      20b9e200 00000f30
Replace   20b9e200 00009090
Comment   MSR 0xE2_xcpm_idle instant reboot(c) Pike R. Alpha
MatchOS   10.12
Disabled   false
```

Edit

```
freqVectorsEdit.sh-master --- bash --- 80x24
[ 8 ] Mac-35C5E88128C7EEAF.plist (Macmini7,1 @ 2700)
[ 9 ] Mac-3C8D08234E554E41.plist (MacBookPro11,2)
[10 ] Mac-42F025E8AC8B274.plist (iMac15,1)
[11 ] Mac-473031E8B893F98.plist (MacBookPro13,1 @ 3100 HWP/3400 HWP)
[12 ] Mac-48F8C7848845591E.plist (Unknown Model)
[13 ] Mac-58619A4880804DA.plist (Unknown Model)
[14 ] Mac-5518B6E5744E2388.plist (Unknown Model @ 3800 HWP/3900 HWP/4100 HWP)
[15 ] Mac-65CE76898165799A.plist (iMac17,1)
[16 ] Mac-66E35819E12D0D85.plist (MacBookPro13,2 @ 3300 HWP/3500 HWP/3600 HWP)
[17 ] Mac-77E87070AF985381.plist (iMac14,3)
[18 ] Mac-7DF21C83ED6977E5.plist (MacBookAir6,2)
[19 ] Mac-81E3E92D06888272.plist (iMac14,4)
[20 ] Mac-937CB26E2E92B881.plist (MacBookAir7,2 @ 2700/3200)
[21 ] Mac-9AE82516C7C6B983.plist (MacBook9,1 @ 2200 HWP/2700 HWP/3100 HWP)
[22 ] Mac-9F18E312C5C28F88.plist (MacBookAir7,1 @ 2700/3200)
[23 ] Mac-A36900CA4E67F1C45.plist (iMac16,1)
[24 ] Mac-ASC67F76ED83188C.plist (MacBookPro13,3 @ 3500 HWP/3600 HWP/3800 HWP)
[25 ] Mac-B889C3757DA9B88D.plist (iMac17,1)
[26 ] Mac-BE8E8AC45FE888CC.plist (MacBook8,1 @ 2400/2600/2900)
[27 ] Mac-D8158D556843C828.plist (iMac17,1)
[28 ] Mac-E43C1C2504888A06.plist (MacBookPro12,1)
[29 ] Mac-F38515888C7DEEEF.plist (Unknown Model @ 2400/2600/2900)
[30 ] Mac-F4842E86C61E91C5.plist (iMac15,1)
[31 ] Mac-FFE5EF878D78A81A.plist (iMac16,2)
```

