

Erledigt

Frage zu Oz GA Z97X-UD5H

Beitrag von „Minsu Kang“ vom 29. April 2017, 08:28

[@griven](#)

The bios (iMac14.2 sierra) doesn't work well.
Bios doesn't cognize PCI-E and PCI slot in OSX.
Even put into graphics card, can't boot.

my motherboard and graphics card are still work perfectly with original bios in Gigabyte website.