

Erledigt

RX 460 not working

Beitrag von „firefly_can_fly“ vom 30. Mai 2017, 22:25

[Zitat von Thogg Niatiz](#)

You should be allowed to correct your own threads titles. I fixed it for you.

sorry, i was using translator and only now manage to find switch for english.

[Zitat von griven](#)

In case of OZ as loader you need to pass the correct Framebuffer and enable OZ ATIIInjection as well. I think for RX460 something like this should do the trick:

Code

```
1. sudo nvram 1F8E0C02-58A9-4E34-AE22-2B63745FA101:DisableAtiInjection=%00sudo nvram 1F8E0C02-58A9-4E34-AE22-2B63745FA101:AtiFramebuffer=Baladi
```

No luck with this, and i basicly use fb in config.plist. No luck with baffin or acre. Maybe someone used OZ with new RX cards?