

Erledigt

RX 460 not working

Beitrag von „griven“ vom 30. Mai 2017, 22:43

Hum I don't have access to one of the newer AMD Cards so no way to test it but maybe the build in ATInjection in OZ may not handle them correctly. Have you tried to inject the Cards properties directly via DSDT instead of using OZ Build in Injection? Also did you check if the Cards Device and Vendor ID is even present in AMD9000Controllers Info.plist?